

# Brand new BlueDiamond Mobile Ready Reader (MRR) is not displaying in the BlueDiamond Toolkit for provisioning

Last Modified on 10/06/2022 4:18 am EDT

## Symptom

Brand new BlueDiamond Mobile Ready Reader (MRR) is not displaying in the BlueDiamond Toolkit for provisioning.

## Resolution

BlueDiamond MRR are being shipped from the factory by default now with Bluetooth disabled. A BDC-ULK and BDC-BLUETOOTH license are required to enable this feature.

## Applies To

BlueDiamond Mobile Ready Readers (LNL-R10320-05TB, LNL-R10325-05TB & LNL-R10330-05TB)

Copyright © 2022 Carrier. All rights reserved.

---