# Lnl-4420 Panel Randomly Reboots

## Symptom

LNL-4420 panels randomly reboot.  Information may be lost such as masking or door schedules after the reboot.

## Resolution

Apply firmware version 1.256 available for download by contacting support

## Applies To

LNL-4420 panels with firmware prior to 1.256

## Additional Information

None