

NGP panels not online when Communication Server running on computer with single-core processor

Last Modified on 10/06/2022 4:15 am EDT

Symptom

If an NGP panel communicates with a Communication Server running on a computer with a single-core processor, that NGP panel might not come online.

This might occur if the computer is either a physical machine with a single-core processor, or a virtual machine with a single processor core assigned to it.

Resolution

To work around this issue, add the following line to the ACS.INI file on the computer running the Communication Server, under the `[CommunicationServer]` section:

```
ComPortThreadLoopDelay=5
```

Save and close the ACS.INI file, then restart the LS Communication Server service.

Applies To

NGP

Additional Information

Note that computers with multiple-core processors are not affected by this issue.
