

# OHNET Receiver does not go online by itself when OHNetworkReceiver service is started after the Communication server

Last Modified on 10/06/2022 4:15 am EDT

## Symptom

The OHNET Receiver (OH -2000) does not go online by itself when the OHNetworkReceiver service is started after the Comm Server

## Resolution

Use the suggested work around - Manually set OHNET offline and then online to establish a connection.

## Applies To

OnGuard 7.6 and its Updates (Update 1, 2 and 3)

## Additional Information

This is already resolved in OnGuard 8.0 and above.

Copyright © 2022 Carrier. All rights reserved.

---