

On the 3U LDVR or LNVR, only one of two network interface cards is listed in the Device Manager

Last Modified on 10/06/2022 4:19 am EDT

Symptom

On the 3U LDVR or LNVR, only one of two network interface cards is listed in the Device Manager.

Resolution

The motherboard of the 3U LDVR/LNVR has two network interface cards (NIC). When only one of them is listed in the Device Manager, the second NIC is disabled by default when the LDVR/LNVR ships from the factory and must be enabled in the BIOS.

- 1) Restart the computer.
- 2) Enter the BIOS
- 2) On the advanced configuration page, enable the second NIC.

Applies To

LDVR (All versions)
LNVR (All versions)

Additional Information

None
