

Daylight Saving Time Should Be Disabled on goVision Recorders (OG-20353/OG-20547)

Last Modified on 10/06/2022 4:19 am EDT

Problem Overview

Daylight Saving Time Should Be Disabled on goVision Recorders (OG-20353/OG-20547)

Detailed Description

Daylight Saving Time (DST) should be disabled on the goVision recorder. OnGuard should be used to control the time for the goVision recorder, DST can be enabled in System Administration. If both OnGuard and the goVision DVR have DST enabled, then the goVision DVR will be off by one hour.

Applies To

OnGuard 2010 (6.4.500)

Additional Information

None
