

Why the playback window time line displays 0.0 fps?

Last Modified on 10/06/2022 4:14 am EDT

Question

Why does the playback window time line display 0.0 fps?

Answer

When viewing recorded video playback in Alarm Monitoring, the frame rate indicated on the playback window time line displays as **0.0 fps** if the video was recorded in time lapse mode.

This is a product limitation.

Applies To

OnGuard (All versions)

Additional Information
