

# OSDP Reader May Have Incorrect LED Display

Last Modified on 10/06/2022 4:15 am EDT

## Problem Overview

OSDP Reader May Have Incorrect LED Display

## Detailed Description

If power is lost to an Open Supervised Device Protocol (OSDP) reader, but power to the Lenel reader interface is maintained, the LED display pattern may be incorrect until some access activity takes place.

## Applies To

OnGuard 2008 Plus (6.1.222) or later

## Additional Information

None

---