LS Web Service crashes after you install the OnGuard Policies 1.1.84 web module.

Last Modified on 10/06/2022 4:18 am EDT

Symptom

LS Web Service crashes after you install the OnGuard Policies 1.1.84 web module. This happens due to a headers file discrepancy between NGINX 1.17.5 and the OnGuard Policies configuration files. The new NGINX version does not support enabling the more_set_headers that exists in Policies.

Resolution

Replacing the more_set_headers with add_headers that also contains the "Always" parameter resolves the issue. Refer to this link for more details: https://github.com/docker/distribution/issues/452

Corrected version of mentioned lines:

add_header 'Access-Control-Allow-Origin: \$cors_http_origin' always; add_header 'Access-Control-Allow-Methods: GET, POST, PUT, DELETE, OPTIONS' always; add header X-Frame-Options DENY always;

Applies To

OnGuard 7.4 Update 3

OnGuard 7.5 Update 2

Additional Information

Copyright © 2022 Carrier. All rights reserved.